

GOVERNMENT OF ANDHRA PRADESH
A B S T R A C T

Public Services- I & CAD Department – certain irregularities were took place in execution of the works under Yogi Vemana Reservoir Project(Maddileru) – Disciplinary action initiated against Sri D.S. Murali, Assistant Executive Engineer (Retd.) – Further action dropped -Orders –issued.

=====

IRRIGATION & CAD (SER.X.1.) DEPARTMENT

G.O.Rt.No. 638

Dt: 01.07.2013.

Read the following:

1. From the CE, Medium Irrigation, Lr.No. DCE3/OT-M2/AEE-3/2341/ 96- Vol.VI, dt. 11.09.2004 and 24.09.2004
2. G.O.Rt.No.1410, I & CAD(Ser.x.1) Dept., dt. 29.9.2005.
3. WSD of Sri D. S. Murali, AE(Retd.) , dt. 17.10.2005
4. G.O.Rt.No.947, I & CAD(Ser.x.1) Dept., dt. 26.6.2006
5. Govt.Memo.No.24985/SerX.1/2004- 16,Dated: 26-06-2006
6. G.O.Rt.No.541, I & CAD(Ser.x.1) Dept., dt. 28.04.2008
7. From the COI, D.O.Lr.No.669/COI-CK/A5/2008,dt.25.8.2008
8. Govt.Memo.No.24985/SerX.1/2004- 21, Dated: 04.09.2008
9. From Sri D.S. Murali, AE(Retd.) explanation dt. 11.11.2008.

&&&

In the reference first cited it has been brought to the notice of the Government, that certain irregularities were took place in execution of the works under Yogivemana Reservoir project (Maddileru). Sri D.S.Murali, Assistant Executive Engineer (Retd.) is one among the responsible engineers.

2. In the reference 2nd read above, disciplinary action has been initiated against Sri D.S.Murali, Assistant Executive Engineer (Retd.) by way of issuing the following articles of charges, inviting his Written Statement Defence.

Articles of charge-I: There is no evidence of reinforcement having been provided in the bucket covering the first four vents from the left end, which is an indication of defective execution.

Articles of charge-II : The concreted spill way profile laid initially from the lower tangent point up to bucket invert was corrected subsequently by laying concrete over the already laid profile with out ensuing proper bond between the two layers and taking adequate precautions. In view of this, the top layer of concrete peeled off causing damage to the spill way profile and bucket during the floods in 10/2001.

Articles of charge-III: The constructed profile does not conform generally to the design profile with lot of undulations from the crest level up to the upper tangent point. Number of undulations indicate that proper supervision was not done during the execution of work.

Articles of charge-IV: Gallery walls and roof were plastered more or less for the entire length of the gallery which indicates that concreting was not done to standards and specifications. Even this plastering does not conform to standards.

Contd. Page 2.

3. In the reference 3rd read above, Sri D.S. Murali, Assistant Executive Engineer (Retd.) has submitted his Written Statement of Defence. After examination of the WSD of the above Charged officer along with other charged officers, it has been decided conduct a detailed inquiry into the charges framed against them. Accordingly, in the reference 4th read above, orders were issued by appointing Sri S. Satyanarayana, Member, COI as Inquiring Authority. Subsequently in the reference 6th read above the case was entrusted to Smt. Chandana Khan, I.A.S., COI, as Inquiring Authority in place of Sri S. Satyanarayana, Member, COI. In the reference 7th read above, the COI has submitted her inquiry report

4. In the reference 8th read above, a copy of the Inquiry report has been communicated to Sri D.S.Murali, Assistant Executive Engineer(Retd.) with a direction to submit his explanation if any thereon. In the reference 9th read above, Sri D.S.Murali, Assistant Executive Engineer (Retd.) has submitted his explanation, stating that the charges are not applicable to him and he was opted for voluntary retirement due to domestic problems and retired on 31.08.2005. He has requested to drop further action against him.

5. After careful examination of the entire matter it has been decided to drop further action against Sri Sri D.S.Murali, Assistant Executive Engineer (Retd.) interms of Rule 9(2)(b) (ii) of A.P.Revised Pension Rules, 1980 Accordingly Government hereby order to drop further action against Sri D.S.Murali, Assistant Executive Engineer (Retd.) in the matter.

6. The Engineer-In-Chief (Administration Wing), Irrigation &CAD Department, Hyderabad shall take further necessary action in the matter accordingly.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

SHAILENDRA KUMAR JOSHI
PRINCIPAL SECRETARY TO GOVERNMENT

To

The Individual through the Engineer-in-Chief (Admn.Wing)

I & CAD Department, Hyderabad.

The Engineer-in-Chief (Admn.Wing),

I & CAD Department, Hyderabad.

Copy to :

The Secretary to V.C., APVC, Hyderabad.

The Accountant General, Andhra Pradesh, Hyderabad.

SC/SF

//FORWARDED: : BY ORDER//

SECTION OFFICER